ಕೆಳಗೆ
ಸದರಿ ಕೆಳಗೆ
ವಾರ್ಡ್ ಸಖ್ಯ
ರಂದು ಒಟ್ಟ
ರೂಂದ 1789
ಪ್ರಕಟಿಸಿದೆ.

BR 826/9.01.2015

1st & final.

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Refer to Measu
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	
	Name of Work:- Maintainance of bore well at Chikkasandra & Shettyhalli in ward no-12. in Shettyhalli Sub-Division.						
	Agency:- S. prakash.						
	W.O:- No. EE/DD/WO/257/13-14		D:- 15/2/2014		Est cost:-	15-0 lakhs	
	JC:- 012-14-000010.						
	Recorded on 31/12/2014.						
I-1	Repairs to Motor Rewinding of Submersible pumpsets with copper insulation Wire of Suitable gauge as per ISI specification With guarantee of 6 months 7.5HP.						
	1) Chikkasandra 14th cross Near Durga prasad clinic	1 No				= 1 No	
	2) Maison layout Near Lakshmi Venkateshwara Service Station	1 No				= 1 No	

Contractor of nature of Agency .....

Commencement of work.....

Full description, etc, of work

2

1) Chikkbanavara Near RNS institute Chikkasandra Near Police ~~Thimmashettyhoo~~

2) Chikkbanvara Main Road Near Apartment

Repair to Motor Re copper. insulation W Specification Wi

26/9.01.2015

ASUREMENT BOOK

Dimensions				Contents	Refere to la Measur
Number 3	Length 4	Breadth 5	Depth 6	7	8
Well at Chikkasandra & Shettyhalli					
halli Sub-Division.					
Di- 15/2/2014 Estcost- 15-0 lakhs					
Recorded on 31/12/2014.					
nding of Submersible pumpsets					
Wire of Suitable gauge as					
With guarantee of 6 months 7.5Hp					
1 NO				= 1 No	
: ND				= 1 No	

M. A. R. 57 (Rule 116)
Measurement Book

No. B 178844

No. .....

f work ..... From ..... To .....

f Contractor of nature of Agency.....

commencement of work.....

Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
2	Number 3	Length 4	Breadth 5	Depth 6	7	8
3) Chikkbanavara Near RNS institute	1 No				= 1 No	
4) Chikkasandra Near Police ~~Thimmashetty~~house	1 No				= 1 No	
5) Chikkbanvara Main Road Near Apartment	1 No				= 1 No	
				7.5 Hp.	5 Nos @ 38250	Rs - 191125-00
Repair to Motor Rewinding of Submersible Pump sets copper. Insulation Wire of Suitable guage as per IS specification with guarantee of 6months 10 Hp.						

EASUREMENT BOOK

Date	Full desc...	Dimensions				Contents	Refe... to ... Measu...
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	
	5) chikkasandra SLN Near plytic factory	1 NO				= 1 NO	
						5 Nos	
						@ 5855:00	A:- 29275:-
I-A.	Replacement of pump bowls						
	1) 7.5 Hp / 16 stage	5 x 10				= 50 Nos	
	2) 10 Hp / 20 stage	19 x 20				= 380 Nos	
	3) 12.5 Hp / 30 stage	5 x 30				= 150 Nos	
						580 Nos	
						@ 308:00	A:- 178640

Verified
EE(D)

Full description, etc, of work

2

Replacement of Intern...
bronze bush.
7.5 Hp / 16 stage
10 Hp / 20 stages
) 12.5 Hp / 30 stages.
(4 Nos from 1 to 4 location mentioned)
Replacement of Oil Seal
) 7.5 Hp / 16 stage

ASUREMENT BOOK

Dimensions				Contents	Refer to l Measur
Number	Length	Breadth	Depth		
3	4	5	6	7	8
1 NO				= 1 NO	
				5 NOS	
				@ 5855:00	M:- 29275:0
50 Nos					
5×10				= 50 NOS	
19×20				= 380 NOS	
5×30				= 150 NOS	
				580 NOS	
				@ 308:00	M:- 178640

M. A. R. 57 (Rule 116)
Measurement Book

No. B

178847

No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
	Number	Length	Breadth	Depth		
2	3	4	5	6	7	8
Replacement of Intermediate Piece (IP) With leaded bronze bush.						
i) 7.5 HP / 18 stage	5×1				= 5 NOS	
ii) 10 HP / 20 stages	19×1				= 19 NOS	
iii) 12.5 HP / 30 stages. (4 Nos from 1 to 4 location mentioned)	4×1				= 4 NOS	
					28 NOS	
					@ 715:00	M:- 20020:00
Replacement of Oil Seal						
i) 7.5 HP / 16 stage	5×2				= 10 NOS	

Verified
31 EE(D)

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Re Mea
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	
	1) 7.5 HP	5x1				= 5.0	
	2) 10.0 HP	19x1				= 19.0	
	3) 12.5 HP	4x1				= 4.0	
						28.0 Nos	
						@ 100=00	
						Rs. 2800	
J-48.	Supplying and fixing ~~Porcelain fuse~~ and Wiring 0 to 600 volts 96 x 96 mm AC volt meter & exisiting pandboard					= 5.0 Nos	
	1) 7.5 HP	5x1				= ~~19.0~~ 57.0 Nos	
	2) 10.0 HP	19x3				= ~~4.00~~ 12.0 Nos	
	3) 12.5 HP	4x3				~~23.0 Nos~~ 74.00 Nos	
						@ 430=00 Rs. 31820	

M. A
M
.....
Work ..... Fro
Contractor of nature of Agency.....
mmencement of work.....

Full description, etc, of work	Numbe
2	3
Supplying and fixing ma	
Exisiting MCB distribut	
fixing materialy and c	
energy cross 3 With short	
10K & complete wiring as	
1) 7.5 HP	5x1
2) 10 HP	19x1
3) 12.5 HP	4x1
Ravi. N.K. 31/12/2014. Total Amount	

ing transport the O_2 diffus
th haemoglobin. Each
d form oxyhaemoglobi
by the haemoglobin
od reaches the t

Contd 825
from 48

JREMENT BOOK

Dimensions				Contents	Ref to Meas
nber 3	Length 4	Breadth 5	Depth 6	7	
x1				=5.0	
x1				=19.0	
x1				=4.0	
				28.0 Nos	
				@ 100=00	Rs. 2800=00
~~reclain fuse~~ and Wiring					
AC voltmeter & existing pandboard					
x1				5.0 NOs	
x3				= ~~57.0~~ 57.0 NOs	
x3				~~12.00~~ 12.0 Nos	
				~~28.0~~ NOs	
				7400	
				@ 430=00	Rs. 3820=00

M. A. R. 57 (Rule 116)
Measurement Book

No. B 178809

..... work ..... From ..... To .....
Contractor of nature of Agency.....
ommencement of work.....

Full description, etc, of work 2	Number 3	Dimensions: Length 4	Dimensions: Breadth 5	Depth 6	Contents 7	Reference to last Measurement 8
Supplying and fixing miniature circuit breakers on exisiting MCB distribution boards using necessary fixing materials and c type curve indicator ON/OFF energy cross 3 with short circuit breaking capacity 10K & complete wiring as required.						
1) 7.5 HP	5x1				= 5.0 NOs	
2) 10 HP	19x1				= 19.0 NOs	
3) 12.5 HP	4x1				= 4.0 NOs	
					28.0 NOs	
Ravi N.K. 31/12/2014. Total Amount 1498375=00				@	1005=00 Rs.	28140=00

cd & FC
31/12

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Remarks
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	
	Certificate:-						
	1) certified that contractor has done the work Satisfactory.						
	2) certified that there is no due work from contractor side.						
	3) Rajesh N.K. 31/12/2014.						
	Audited and admitted for Rs. 149837=00						
	Passed by Cheque for Rs. 140697=00						
	(.....)						
	by adjustment Rs. 9140/=00						
	Accounts Superintendent / Executive Engineer						
	B.B.M.P., Hegganahalli Division						

31/12/14

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು-

25/5/15

1st & Final.

Work Maintainance of bo
Shettyhalli Sub-Divisi
Contractor of nature of Agency.....
Commencement of work... No EE/D

Full description, etc, of work
2
epair to Motor Rewindi
opper insulation. Hire
With Guarantee o
7.5HP
Abbigere Near Lakshmi temple
Abbigere Shivanarjappa
layout pipe line Road
Abbigere patelappa layout
1st cross
Abbigere Janatha Colony
pump house

SUREMENT BOOK

Dimensions				Contents	Ref. to last Measurement
Number 3	Length 4	Breadth 5	Depth 6	7	
has done the work satisfactory. due work from Contractor s/dr.					

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

31/12/14

25/5/15

1st & final.

M. A. R. 57 (Rule 116)
Measurement Book

No. B

BR 825/9.1.2015

178861

work Maintainance of bore well at Abbigere and Medarahalli in ward no-12 From ..... To .....
shettyhalli sub-Division

Contractor of nature of Agency..... S. prakash Sc:-012-14-000009 Est cost:- 15.0 lakhs

ommencement of work..... No EE/DD/No/258/13-14 Dt:-15/2/14.

Full description, etc, of work 2	Dimensions				Contents 7	Reference to last Measurement 8
	Number 3	Length 4	Breadth 5	Depth 6		
Repair to Motor Rewinding of Submersible pumpsets with copper insulation Wire of Suitable Gauge as per IS/specifications With Guarantee of 6 months 7.5 HP.	Recorded on 31/12/2014.					
— 7.5HP						
1) Abbigere Near Lakshmi temple	1 No				= 1 NO	
2) Abbigere Shivananjappa layout pipe line Road	1				= 1 NO	
3) Abbigere patelappa layout 1st cross	1				= 1 NO	
4) Abbigere Janatha Colony pump house	1				= 1 NO	
					4 Nos @ 3822=50	Agt:- 15290=00